

REPLACEMENT SHEET
Serial No. 10/723,407

Title: REFORMER EXERCISE APPARATUS ANCHOR BAR ASSEMBLY
Docket No.: 75886.010300
Mailing Date: March 16, 2006
Express Mailing Label No.: EV 641289376 US




FIG.7